

# Hardtop Pro Comp B

# Section 1. Identification

GHS product identifier	: Hardtop Pro Comp B
Other means of identification	: Not available.
Product code	: 27221
Product description	: Paint.
Product type	: Liquid.

Relevant identified uses of the substance or mixture and uses advised against

Identified uses		
Use in coatings - Professional us	se la	
Manufacturing country :	Jotun Thailand Limited 700/353 Amata Nakorn Industrial Estate (BIP 2) Moo 6, Tumbol Donhualoh, Amphur Muang Chonburi Chonburi 20000 Thailand Phone: + 66 2 022 9888 Fax: + 66 2 022 9888 , + 66 38 214 375 SDSJotun@jotun.com	
Emergency telephone number :	Jotun Thailand Limited Phone: + 66 2 022 9888 ext. 2100, 2400, 2402	

# Section 2. Hazards identification

Classification of the substance or mixture	: FLAMMABLE LIQUIDS - Category 3 SERIOUS EYE DAMAGE/EYE IRRITATION - Category 1
GHS label elements	
Hazard pictograms	
Signal word	: Danger.
Hazard statements	: H226 - Flammable liquid and vapour. H318 - Causes serious eye damage.
Precautionary statements	
Prevention	<ul> <li>P280 - Wear eye or face protection.</li> <li>P210 - Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.</li> </ul>
Response	<ul> <li>P305 + P351 + P338, P310 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or doctor.</li> </ul>
Storage	: P403 + P235 - Store in a well-ventilated place. Keep cool.
Disposal	: P501 - Dispose of contents and container in accordance with all local, regional, national and international regulations.

## Section 2. Hazards identification

Other hazards which do not	: None known.
result in classification	

## Section 3. Composition/information on ingredients

Substance/mixture	: Mixture
Other means of identification	: Not available.
CAS number/other identifiers	
CAS number	: Not applicable.

CAS number	i not applicable.		
EC number	: Mixture.		
Product code	: 27221		
Ingredient name		%	CAS number
silane, trimethyoxy[3-(o	oxiranyl-methoxy)propyl]-	≥10 - <25 ≤10	2530-83-8 123-86-4

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

## Section 4. First aid measures

### Description of necessary first aid measures

Eye contact	:	Get medical attention immediately. Call a poison center or physician. Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Continue to rinse for at least 10 minutes. Chemical burns must be treated promptly by a physician.
Inhalation	:	Get medical attention immediately. Call a poison center or physician. Remove victim to fresh air and keep at rest in a position comfortable for breathing. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband.
Skin contact	:	Get medical attention immediately. Call a poison center or physician. Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Wash contaminated clothing thoroughly with water before removing it, or wear gloves. Continue to rinse for at least 10 minutes. Chemical burns must be treated promptly by a physician. Wash clothing before reuse. Clean shoes thoroughly before reuse.
Ingestion	:	Get medical attention immediately. Call a poison center or physician. Wash out mouth with water. Remove dentures if any. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Stop if the exposed person feels sick as vomiting may be dangerous. Do not induce vomiting unless directed to do so by medical personnel. If vomiting occurs, the head should be kept low so that vomit does not enter the lungs. Chemical burns must be treated promptly by a physician. Never give anything by mouth to an unconscious person. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband.
Most important symptoms/effect Potential acute health effects	: <u>ts</u> ,	acute and delayed
Eye contact		Causes serious eye damage.
Inhalation	- 21	No known significant effects or critical hazards.

Innalation	: No known significant effects or critical nazards.	
Date of issue	: 20.07.2022	2/10

# Section 4. First aid measures

Skin contact	: No known significant effects or critical hazards.
Ingestion	: No known significant effects or critical hazards.
Over-exposure signs/sympt	<u>oms</u>
Eye contact	: Adverse symptoms may include the following: pain watering redness
Inhalation	: No specific data.
Skin contact	: Adverse symptoms may include the following: pain or irritation redness blistering may occur
Ingestion	: Adverse symptoms may include the following: stomach pains
Indication of immediate medi	cal attention and special treatment needed, if necessary
Notes to physician	<ul> <li>Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.</li> </ul>
Specific treatments	: No specific treatment.
Protection of first-aiders	: No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.

See toxicological information (Section 11)

Section 5. Firefighting measures		
Extinguishing media		
Suitable extinguishing media	: Use dry chemical, CO <sub>2</sub> , water spray (fog) or foam.	
Unsuitable extinguishing media	: Do not use water jet.	
Specific hazards arising from the chemical	: Flammable liquid and vapour. Runoff to sewer may create fire or explosion hazard. In a fire or if heated, a pressure increase will occur and the container may burst, with the risk of a subsequent explosion.	
Hazardous thermal decomposition products	: Decomposition products may include the following materials: carbon dioxide carbon monoxide metal oxide/oxides	
Special protective actions for fire-fighters	: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.	
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.	

# Section 6. Accidental release measures

Personal precautions, prote	ctive equipment and emergency procedures
For non-emergency personnel	: No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilt material. Shut off all ignition sources. No flares, smoking or flames in hazard area. Do not breathe vapour or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment.

Date of is	sue : 20.07.2022	3/10
------------	------------------	------

### Section 6. Accidental release measures

For emergency responders	:	If specialised clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".
Environmental precautions	:	Avoid dispersal of spilt material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
Methods and material for cont	ainn	nent and cleaning up
Small spill	:	Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor.
Large spill	:	Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Approach the release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see Section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilt product. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

### Section 7. Handling and storage

Precautions for safe handling : Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures.

Conditions for safe storage, including any incompatibilities : Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and wellventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Eliminate all ignition sources. Separate from oxidising materials. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabelled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use.

### Section 8. Exposure controls/personal protection

#### **Control parameters**

Occupational exposure limits		
Ingredient name		Exposure limits
n-butyl acetate		ACGIH TLV (United States, 1/2021). STEL: 150 ppm 15 minutes. TWA: 50 ppm 8 hours.
Recommended monitoring procedures	: If this product contains ingredients with exposure limits, personal, workpla atmosphere or biological monitoring may be required to determine the efference of the ventilation or other control measures and/or the necessity to use reprotective equipment. Reference should be made to appropriate monitoring standards. Reference to national guidance documents for methods for the determination of hazardous substances will also be required.	

## Section 8. Exposure controls/personal protection

Appropriate engineering         : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls is also meed to keep gas, spour or dust concentrations below any lower explosive controls also meed to keep gas, spour or dust concentrations below any lower explosive limits. Use explosion-proof ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fure scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.           Individual protection measures         : Wash hards, forearms and face thoroughly after handling chemical products, before caing, amoxing and using the lawary and at the end of the working period. Wash contaminated delibing before reusing. Ensure thally everash atations and safety showers are close to the working and using a set works table to location.           Eyerface protection         : Safety everas complying to EN 166 should be used when a risk assessment indicates a high-degree of protection chemical spash gogles and/ or face sheid. If inhalation hazards exist, a full-face respirator may be required instead.           Skin protection         : Chemical-resistant, improtous gloves acomplying with an approved standard should be work at all times when handling chemical products if a risk assessment indicates his is necessary. Considering the protection chemical spash gogles and/ or face sheid. If inhalation hazards exist, a full-face respirator may be required instead.           Skin protection         : Chemical-resistant, improtous gloves acomptiving with an approved standard should be work at all times when handling chemical products. The instructops and indive are stall relations in anteriats th		
Environmental exposure controls         : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fund scoubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.           Individual protection measures         : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated dolbing. Wash contaminated dolbing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.           Eye/face protection         : Safety eyewear complying to EN 166 should be used on unless the assessment indicates a higher degree of protection: chemical splash goggles and/ or face shield. If inhalation hazards exist, a full-face respirator may be required instead.           Skin protection         : Onemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove maintafurer, check during use that the gloves are still relating their protective consisting of several substances, the protection inme of the gloves cannot be accurately estimated.           There is no one glove material or combination of metricals that will give unlinted resistance to any individual or combination of metricals that will give unlinted resistance to any individual or combination of themicals. The breakthrough time must be foracert hourds be noted.           Ware sutable gloves the replaced regulary and if there is		ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapour or dust concentrations below any lower explosive
Hyglene measures       : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eyerface protection       : Safety eyewear complying to EN 166 should be used when a risk assessment indicates this is necessary to avoid exposure to liquid explashes, mists, gases or dusts. If contact is possible, the following protection should be worm, unless the assessment indicates a higher degree of protection chemical splash gogles and/ or face shield. If inhalation hazards exist, a full-face respirator may be required instead.         Skin protection       : Chemical-resistant, impervious gloves complying with an approved standard should be worm at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough time protective properties. It should be noted that the time to breakthrough time must be glove manufacturer on use, stimated.         There is no one glove material or combination of materials that will give unlimited resistance to any individual or combination of chemicals. The breakthrough time must be gloved must be followed.         Gloves should be replaced regularly and if there is any sign of damage to the glove material.         Always ensure that gloves are free from defects and that they are stored and used correctly.         The berofitmenance. </td <td></td> <td>: Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process</td>		: Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process
eating, smoking and using the lavatory and at the end of the working period.         Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.         Eye/face protection       : Safety eyewear complying to EN 166 should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or duss. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: chemical splash goggles and/ or face shield. If inhalation hazards exist, a full-face respirator may be required instead.         Skin protection       : Ohemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective, consisting of several substances, the protection time to breakthrough firm any glove material may be a different to different glove material or combination of naterials that will give unlimited resistance to any individual or combination of materials that will give unlimited resistance to any individual or combination of materials that will give unlimited resistance to any individual or combination of materials that will give unlimited resistance to any individual or combination of damage to the glove material. Always ensure that gloves are free from defects and that they are stored and used correctly. The performance or effectiveness of the glove may be reduced by physical/chemical damage and poor maintenance.         Barite or cowareal apove trainel and poor maintenance. <t< td=""><td>Individual protection measures</td><td></td></t<>	Individual protection measures	
Indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: chemical splash goggles and/ or face shield. If inhalation hazards exist, a full-face respirator may be required instead.         Skin protection <ul> <li>Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the glove manufacturer, check during use that gloves and acturers. In the case of mixtures, consisting of several substances, the protection of chemicals. The breakthrough time must be greater than the end use time of the product. The instructions and information provided by the glove manufacturer on use, storage, maintenance and replacement must be followed. Gloves should be replaced regularly and if there is any sign of damage to the glove material. Always ensure that gloves are free from defects and that they are stored and used correctly. The performance or effectiveness of the glove may be reduced by physical/chemical damage and poor maintenance. Barrier creams may help to protect the exposed areas of the skin but should not be applied once exposure has occurred.         Wear suitable gloves tested to EN374.       Recommended, gloves(breakthrough time) &gt; 8 hours: Teflon, polyvinyl alcohol (PVA May be used, gloves(breakthrough time) &gt; 1 hour: nitrile rubber, PvC Not recommended, gloves(breakth</li></ul>	Hygiene measures	eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and
Hand protection       : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.         There is no one glove material or combination of materials that will give unlimited resistance to any individual or combination of chemicals. The breakthrough time must be greater than the end use time of the product. The instructions and information provided by the glove manufacturer on use, storage, maintenance and replacement must be followed.         Gloves should be replaced regularly and if there is any sign of damage to the glove material.         Always ensure that gloves are free from defects and that they are stored and used correctly.         The performance or effectiveness of the glove may be reduced by physical/chemical damage and poor maintenance.         Barrier creams may help to protect the exposed areas of the skin but should not be applied once exposure has occurred.         Wear suitable gloves (breakthrough time) < 1 hours: Teflon, polyvinyl alcohol (PVA May be used, gloves(breakthrough time) < 1 hour: nitrile rubber, neoprene, Viton@, PE	Eye/face protection	indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: chemical splash goggles and/ or face shield. If inhalation hazards exist, a full-face respirator may be required
be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.         There is no one glove material or combination of materials that will give unlimited resistance to any individual or combination of naterials that will give unlimited resistance to any individual or combination of chemicals. The breakthrough time must be greater than the end use time of the product. The instructions and information provided by the glove manufacturer on use, storage, maintenance and replacement must be followed.         Gloves should be replaced regularly and if there is any sign of damage to the glove material.         Always ensure that gloves are stife from defects and that they are stored and used correctly.         The performance or effectiveness of the glove may be reduced by physical/chemical damage and poor maintenance.         Barrier creams may help to protect the exposed areas of the skin but should not be applied once exposure has occurred.         Wear suitable gloves (breakthrough time) > 8 hours: Teflon, polyvinyl alcohol (PVA May be used, gloves(breakthrough time) > 1 hour: nitrile rubber, PVC Not recommended, gloves(breakthrough time) > 1 hour: nitrile rubber, NVC Not new, PE         Body protection       : Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist be	Skin protection	
resistance to any individual or combination of chemicals. The breakthrough time must be greater than the end use time of the product. The instructions and information provided by the glove manufacturer on use, storage, maintenance and replacement must be followed. Gloves should be replaced regularly and if there is any sign of damage to the glove material. Always ensure that gloves are free from defects and that they are stored and used correctly. The performance or effectiveness of the glove may be reduced by physical/chemical damage and poor maintenance. Barrier creams may help to protect the exposed areas of the skin but should not be applied once exposure has occurred. Wear suitable gloves tested to EN374. Recommended, gloves(breakthrough time) > 8 hours: Teflon, polyvinyl alcohol (PVA May be used, gloves(breakthrough time) > 8 hours: Teflon, polyvinyl alcohol (PVA May be used, gloves(breakthrough time) > 1 hour: nitrile rubber, neoprene, Viton®, PEBody protection:Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. When there is a risk of ignition from static discharges, clothing should include anti-static overalls, boots and gloves.Other skin protection:Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and the risks involved and should be approved by a specialist before handling this product.Respiratory protection:Appropriate footwear and any additional skin protection measures should be approved by a specialist before handling this product.Respiratory protection:Appropriate footwear and any additional skin protection measures should be <td>Hand protection</td> <td>be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately</td>	Hand protection	be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately
Always ensure that gloves are free from defects and that they are stored and used correctly.         The performance or effectiveness of the glove may be reduced by physical/chemical damage and poor maintenance.         Barrier creams may help to protect the exposed areas of the skin but should not be applied once exposure has occurred.         Wear suitable gloves tested to EN374.         Recommended, gloves(breakthrough time) > 8 hours: Teflon, polyvinyl alcohol (PVA May be used, gloves(breakthrough time) < 8 hours: 4H, butyl rubber, PVC Not recommended, gloves(breakthrough time) < 1 hour: nitrile rubber, neoprene, Viton®, PE		resistance to any individual or combination of chemicals. The breakthrough time must be greater than the end use time of the product. The instructions and information provided by the glove manufacturer on use, storage, maintenance and replacement must be followed. Gloves should be replaced regularly and if there is any sign of damage to the glove
Barrier creams may help to protect the exposed areas of the skin but should not be applied once exposure has occurred.         Wear suitable gloves tested to EN374.         Recommended, gloves(breakthrough time) > 8 hours: Teflon, polyvinyl alcohol (PVA May be used, gloves(breakthrough time) 4 - 8 hours: 4H, butyl rubber, PVC Not recommended, gloves(breakthrough time) < 1 hour: nitrile rubber, neoprene, Viton®, PE		Always ensure that gloves are free from defects and that they are stored and used correctly.
Recommended, gloves(breakthrough time) > 8 hours: Teflon, polyvinyl alcohol (PVA May be used, gloves(breakthrough time) 4 - 8 hours: 4H, butyl rubber, PVC Not recommended, gloves(breakthrough time) < 1 hour: nitrile rubber, neoprene, Viton®, PE		Barrier creams may help to protect the exposed areas of the skin but should not be
Other skin protectionRespiratory protectionBased on the hazard and potential for exposure, select a respirator that meets the appropriate standard or certification. Respirators must be used according to a respiratory protection program to ensure proper fitting, training, and other important aspects of use.		Recommended, gloves(breakthrough time) > 8 hours: Teflon, polyvinyl alcohol (PVA May be used, gloves(breakthrough time) 4 - 8 hours: 4H, butyl rubber, PVC Not recommended, gloves(breakthrough time) < 1 hour: nitrile rubber, neoprene,
<ul> <li>Respiratory protection</li> <li>Based on the hazard and potential for exposure, select a respirator that meets the appropriate standard or certification. Respirators must be used according to a respiratory protection program to ensure proper fitting, training, and other important aspects of use.</li> </ul>	Body protection	being performed and the risks involved and should be approved by a specialist before handling this product. When there is a risk of ignition from static electricity, wear anti-static protective clothing. For the greatest protection from static
appropriate standard or certification. Respirators must be used according to a respiratory protection program to ensure proper fitting, training, and other important aspects of use.	Other skin protection	selected based on the task being performed and the risks involved and should be
Date of issue : 20.07.2022 5/10	Respiratory protection	: Based on the hazard and potential for exposure, select a respirator that meets the appropriate standard or certification. Respirators must be used according to a respiratory protection program to ensure proper fitting, training, and other important
	Date of issue	: 20.07.2022 5/10

### Section 8. Exposure controls/personal protection

If workers are exposed to concentrations above the exposure limit, they must use a respirator according to EN 140. Use respiratory mask with charcoal and dust filter when spraying this product, according to EN 14387(as filter combination A2-P2). In confined spaces, use compressed-air or fresh-air respiratory equipment. When use of roller or brush, consider use of charcoalfilter.

## Section 9. Physical and chemical properties

Appearance		
Physical state	: Liquid.	
Colour	: Colourless.	
Odour	: Characteristic.	
Odour threshold	: Not available.	
рН	Not applicable.	
Melting point	: Not applicable.	
Boiling point	: Lowest known value: 126°C (258.8°F) (n-butyl acetate).	
Flash point	: Closed cup: 28°C (82.4°F)	
Burning time	: Not applicable.	
Burning rate	: Not applicable.	
Evaporation rate	: 1 (n-butyl acetate) compared with butyl acetate	
Flammability (solid, gas)	: Not applicable.	
Lower and upper explosive (flammable) limits	: 0.43 - 7.6%	
Vapour pressure	: Highest known value: 1.5 kPa (11.3 mm Hg) (at 20°C) (n-butyl acetate). Weighte average: 0.46 kPa (3.45 mm Hg) (at 20°C)	)d
Vapour density	: Highest known value: 4 (Air = 1) (n-butyl acetate).	
Relative density	: 1.21 g/cm <sup>3</sup>	
Solubility	: Insoluble in the following materials: cold water and hot water.	
Partition coefficient: n-octanol/ water	: Not available.	
Auto-ignition temperature	: Lowest known value: 400°C (752°F) (silane, trimethyoxy[3-(oxiranyl-methoxy)prop).	pyl]-
Decomposition temperature	: Not available.	
SADT	: Not available.	
Viscosity	: Kinematic (40°C): >20.5 mm²/s (>20.5 cSt)	
Aerosol product		

# Section 10. Stability and reactivity

Reactivity	: No specific test data related to reactivity available for this product or its ingredients.
Chemical stability	: The product is stable.
Possibility of hazardous reactions	: Under normal conditions of storage and use, hazardous reactions will not occur.
Conditions to avoid	: Avoid all possible sources of ignition (spark or flame). Do not pressurise, cut, weld, braze, solder, drill, grind or expose containers to heat or sources of ignition.
Incompatible materials	<ul> <li>Keep away from the following materials to prevent strong exothermic reactions: oxidising agents, strong alkalis, strong acids.</li> </ul>
Hazardous decomposition products	: Under normal conditions of storage and use, hazardous decomposition products should not be produced.

# Section 11. Toxicological information

### Information on toxicological effects

#### Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
n-butyl acetate	LC50 Inhalation Vapour LD50 Dermal LD50 Oral	Rabbit	>21.1 mg/l >17600 mg/kg 13100 mg/kg	4 hours - -

#### Irritation/Corrosion

Product/ingredient name	Result	Species	Score	Exposure	Observation
silane, trimethyoxy[3- (oxiranyl-methoxy)propyl]-	,	Mammal - species unspecified	-	-	-

### **Sensitisation**

Not available.

#### **Mutagenicity**

Not available.

#### **Carcinogenicity**

Not available.

#### **Reproductive toxicity**

Not available.

#### **Teratogenicity**

Not available.

#### Specific target organ toxicity (single exposure)

Name	- 37	Route of exposure	Target organs
n-butyl acetate	Category 3	-	Narcotic effects

#### Specific target organ toxicity (repeated exposure)

Not available.

### Aspiration hazard

Not available.

#### Potential acute health effects

Eye contact	: Causes serious eye damage.
Inhalation	: No known significant effects or critical hazards.
Skin contact	: No known significant effects or critical hazards.
Ingestion	: No known significant effects or critical hazards.

#### Symptoms related to the physical, chemical and toxicological characteristics

Inhalation	: No specific data.
Ingestion	: Adverse symptoms may include the following: stomach pains
Skin contact	: Adverse symptoms may include the following: pain or irritation redness blistering may occur
Eye contact	: Adverse symptoms may include the following: pain watering redness

#### Potential chronic health effects

Date of issue	: 20.07.2022	7/10

## Section 11. Toxicological information

General	: No known significant effects or critical hazards.
Carcinogenicity	: No known significant effects or critical hazards.
Mutagenicity	: No known significant effects or critical hazards.
Teratogenicity	: No known significant effects or critical hazards.
Developmental effects	: No known significant effects or critical hazards.
Fertility effects	: No known significant effects or critical hazards.

#### Numerical measures of toxicity

Acute toxicity estimates

Not available.

## Section 12. Ecological information

### Toxicity

Not available.

#### Persistence and degradability

Product/ingredient name	Aquatic half-life	Photolysis	Biodegradability
silane, trimethyoxy[3- (oxiranyl-methoxy)propyl]-	-	-	Not readily

### **Bioaccumulative potential**

Product/ingredient name	LogPow	BCF	Potential
n-butyl acetate	2.3	-	low

Mobility in soil Soil/water partition coefficient (K <sub>oc</sub> )	: Not available.
Other adverse effects	: No known significant effects or critical hazards.

## Section 13. Disposal considerations

Disposal methods	: The generation of waste should be avoided or minimised wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non- recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Vapour from product residues may create a highly flammable or explosive atmosphere inside the container. Do not cut, weld or grind used containers unless they have been cleaned thoroughly internally. Avoid dispersal of spilt material and runoff and contact with spill waterwaye, drains and sewers
	soil, waterways, drains and sewers.

### Section 14. Transport information

Section 14. Transport information			
	UN	IMDG	IATA
UN number	UN1263	UN1263	UN1263
UN proper shipping name	Paint	Paint	Paint
Transport hazard class(es)	3	3	3
Packing group	Ш	Ш	Ш
Environmental hazards	No.	No.	No.
Special precautions for user	<b>Transport within user's</b> <b>premises:</b> always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.	<b>Transport within user's</b> <b>premises:</b> always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.	<b>Transport within user's</b> <b>premises:</b> always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.
Additional information	-	Emergency schedules F-E, S-E	-

Transport in bulk according to : Not available. IMO instruments

ADR / RID

: Tunnel restriction code: (D/E)

Hazard identification number: 30

### Section 15. Regulatory information

Hazardous Substance Act B.E. 2535	(1992)

<u>Type</u>

Ingredient name

<u>Type</u>

<u>Authority</u>

**Conditions** 

No known specific national and/or regional regulations applicable to this product (including its ingredients).

## Section 16. Other information

<u>History</u>		
Date of printing	1	20.07.2022
Date of issue/Date of revision	1	20.07.2022
Date of previous issue	:	28.05.2020
Version	:	1.13
Key to abbreviations	:	ADN = European Provisions concerning the International Carriage of Dangerous Goods by Inland Waterway ADR = The European Agreement concerning the International Carriage of Dangerous Goods by Road ATE = Acute Toxicity Estimate BCF = Bioconcentration Factor GHS = Globally Harmonized System of Classification and Labelling of Chemicals IATA = International Air Transport Association IBC = Internediate Bulk Container IMDG = International Maritime Dangerous Goods MARPOL = International Convention for the Prevention of Pollution From Ships,
Date of issue		: 20.07.2022 9/10

### Section 16. Other information

1973 as modified by the Protocol of 1978. ("Marpol" = marine pollution) RID = The Regulations concerning the International Carriage of Dangerous Goods by Rail UN = United Nations LogPow = logarithm of the octanol/water partition coefficient

#### References

: Not available.

✓ Indicates information that has changed from previously issued version.

#### Notice to reader

The information in this document is given to the best of Jotun's knowledge, based on laboratory testing and practical experience. Jotun's products are considered as semi-finished goods and as such, products are often used under conditions beyond Jotun's control. Jotun cannot guarantee anything but the quality of the product itself. Minor product variations may be implemented in order to comply with local requirements. Jotun reserves the right to change the given data without further notice.

Users should always consult Jotun for specific guidance on the general suitability of this product for their needs and specific application practices.

If there is any inconsistency between different language issues of this document, the English (United Kingdom) version will prevail.